

QUICK INSTALLATION GUIDE



CONTACT

KFA AG
 Industriestraße 40
 P.O. Box 1224
 40874 Lohr a. M.
 GERMANY

PHONE +49 91433 1-10 11 00
E-MAIL info@kfa.de
WEB www.kfa.de

KFA2

6-axis TDR sensor with single rod, with near or contact probe for continuous level measurement and point level detection in liquids and light solids, with wiring and mounting guide.

DOCUMENT DESCRIPTION

This quick installation guide gives instructions for mounting, wiring, and level configuration of KFA2. This will be sufficient to achieve a fully functional sensor in most applications. For further details and advanced configuration of KFA2, please contact your local distributor or KFA directly.

INSTALLATION PROCEDURE

